


ALCOHOL SENSOR RECOMMENDATIONS



1. Low humidity areas may be dry desert, or cold climates with prolonged sub-zero °C temperatures.
2. Peak measurement may be preferred to integration in extreme environments.